

Dt.15.04.2021

EVALUATION REPORT**Tender no.609/RC/TNMSC/ENGG/2020, Dt.09.10.2020****Tender for Fixing Rate contract for supply of VDRL Rotator, Hot Air Oven and Digital Incubator to various Govt. Institutions****Sch.no.1 VDRL Rotator – 25 nos. tentative quantity**

Sl. No	Name of the Equipment and Bidder	Responsiveness of bidders		Reason for rejection
		Technical evaluation report	Commercial evaluation report	
1	M/s. Alan Medical & Laboratory Products, Make: REMI, Model: RS-12 Plus	Responsive	Responsive	-----
2	M/s. Universal Agencies, Make: Rotek, Model: RVD-R01 (SPL)	Responsive	Non-responsive	<ul style="list-style-type: none"> • Did not furnish the enduser certificate with supporting documents like PO, Installation report for the same make to meet the qualification criteria. The documents furnished are for different make. • Did not furnish the manufacturing capacity at least 450 Nos. certified by licensing authority / chartered accountant.
3	M/s. Span Surgical Co, Make: MVTEX, Model: M-Rotate 9	Responsive	Non-responsive	<ul style="list-style-type: none"> • Did not furnish the enduser certificate with supporting documents like PO, Installation report for the same make to meet the qualification criteria.
4	M/s. Ponmani & Co, Make: Labtech	Non-responsive on bid security		

Sch.no.2 Hot Air Oven – 25 nos. tentative quantity

Sl. No	Name of the Equipment and Bidder	Responsiveness of bidders		Reason for rejection
		Technical evaluation report	Commercial evaluation report	
1	M/s. M.C. Dalal & Co, Make: Dalal, Model: MCD 102D	Responsive	Responsive	-----

Sl. No	Name of the Equipment and Bidder	Responsiveness of bidders		Reason for rejection
		Technical evaluation report	Commercial evaluation report	
2	M/s. Servell Bio Engineers Pvt. Ltd, Make: Hasthas Scientific Instruments, Model: SE-HO-S-90	Responsive	Responsive	-----
3	M/s. M.R. Enterprises, Make: Tempo, Model: TI-128B	Responsive	Non-Responsive	<ul style="list-style-type: none"> • Did not furnish the enduser certificate with supporting documents like PO, Installation report for the same make to meet the qualification criteria. The documents furnished are only for manufacturer supply. • Did not agree for delivery schedule as per bid document. • Did not furnish the cash credit limit with their bankers.
4	M/s. Universal Agencies, Make: Rotek, Model: RHO-18	Responsive	Non-Responsive	<ul style="list-style-type: none"> • Did not furnish the enduser certificate with supporting documents like PO, Installation report for the same make to meet the qualification criteria. The documents furnished are for different make. • Did not furnish the manufacturing capacity at least 450 Nos. certified by licensing authority / chartered accountant.
5	M/s. Span Surgical Co, Make: MVTEX, Model: MDC-99	Responsive	Non-Responsive	<ul style="list-style-type: none"> • Did not furnish the enduser certificate with supporting documents like PO, Installation report for the same make to meet the qualification criteria.
6	M/s. Technico Laboratory Products Pvt. Ltd, Make: Technico	Non-Responsive	Responsive	<ul style="list-style-type: none"> • Against the requirement size: L x W x H 45x45x45 cm – offered 35x35x35 cm • Against the capacity: 95 L – offered 45 Litres
7	M/s. Ponmani & Co, Make: Labtech	Non-responsive on bid security		

Sch.no.3 Digital Incubator – 25 nos. tentative quantity

Sl. No	Name of the Equipment and Bidder	Responsiveness of bidders		Reason for rejection
		Technical evaluation report	Commercial evaluation report	
1	M/s. M.C. Dalal & Co, Make: Dalal, Model: 104D	Responsive	Responsive	-----
2	M/s. Servell Bio Engineers Pvt. Ltd, Make: Hasthas Scientific Instruments, Model: 1224D/10	Responsive	Responsive	-----
3	M/s. Technico Laboratory Products Pvt. Ltd, Make: Technico	Responsive	Responsive	-----
4	M/s. M.R. Enterprises, Make: Tempo, Model: TI-90 D SPL	Responsive	Non-Responsive	<ul style="list-style-type: none"> • Did not furnish the enduser certificate with supporting documents like PO, Installation report for the same make to meet the qualification criteria. The documents furnished are only for manufacturer supply. • Did not agree for delivery schedule as per bid document. • Did not furnish the cash credit limit with their bankers.
5	M/s. Universal Agencies, Make: Rotek, Model: RIM 24 SPL	Responsive	Non-Responsive	<ul style="list-style-type: none"> • Did not furnish the enduser certificate with supporting documents like PO, Installation report for the same make to meet the qualification criteria. The documents furnished are for different make. • Did not furnish the manufacturing capacity at least 450 Nos. certified by licensing authority / chartered accountant.
6	M/s. Span Surgical Co, Make: MVTEX, Model: M-Incubation 3	Responsive	Non-Responsive	<ul style="list-style-type: none"> • Did not furnish the enduser certificate with supporting documents like PO, Installation report for the same make to meet the qualification criteria.
7	M/s. Ponmani & Co, Make: Labtech	Non-responsive on bid security		