

24.05.2024

**Tender Ref : E1111/FUR/RC/TNMSC/ENGG/2023, DT: 07.12.2023**

**Online Tender for Fixing Rate Contract for Supply of Baby Trolley,  
Twin Transfer Trolley, Examination Couch and Bedside Locker To  
Various Govt. Institutions.**

**RESULT OF EVALUATION**

**Sch.I-Baby Trolley:-**

Brief Description	Name of the bidders	Responsiveness		Reason for rejection
		Technical Evaluation	Commercial evaluation	
<b>Baby Trolley</b>	M/s.BHN Surgicals Private Limited, <b>Make-</b> BHN Surgicals Private Limited <b>Model-</b> MW-06	Non-Responsive	Responsive	<b>Technical Evaluation:</b> Not demonstrated
	M/s.Carewell Medical Systems <b>Make-</b> Carewell <b>Model-</b> CMS047	Responsive	Responsive	-----
	M/s.Imedfurns Private Limited <b>Make-</b> Imedfurns Private Limited <b>Model-</b> IMED4007T	Responsive	Responsive	-----
	M/s.Phoenix Medical Systems Pvt. Ltd. <b>Make-</b> Phoenix Medical Systems Pvt. Ltd. <b>Model-</b> BAS100	Responsive	Responsive	-----
	M/s.R. Madhusudhanan <b>Make-</b> R.Madhusudhanan <b>Model-</b> Madhu-025	Non-Responsive	Responsive	<b>Technical Evaluation:</b> Based on the specialist report the bidder is not meeting the following: 1. New born bed should be at least 75cm×52cm. 2. Trolley should have 8mm thick Acrylic side panel should be at least 16cm above the mattress. The acrylic side panel should be hinged with latches to lock in position.

Brief Description	Name of the bidders	Responsiveness		Reason for rejection
		Technical Evaluation	Commercial evaluation	
	M/s.Solokrafts Industries <b>Make-</b> Solokrafts Industries <b>Model-</b> KRAFT 502A	Non-Responsive	Responsive	<b>Technical Evaluation:</b> Based on the specialist report the bidder is not meeting the following: 1. Trolley should have 8mm thick Acrylic side panel should be at least 16cm above the mattress. The acrylic side panel should be hinged with latches to lock in position. 2. Trolley should have tiltable infant bed to 8 degree on either side without lifting the mattress. 3. Should have provision to take X-ray without disturbing the baby.

**Sch.II-Twin Transfer Trolley:-**

Brief Description	Name of the bidders	Responsiveness		Reason for rejection
		Technical Evaluation	Commercial evaluation	
<b>Twin Transfer Trolley</b>	M/s.BHN Surgicals Private Limited <b>Make-</b> BHN Surgicals Private Limited <b>Model-</b> MW-175	Responsive	Responsive	-----
	M/s.Prince Hospital Furniture (mfg) Co., <b>Make-</b> Prince <b>Model-</b> PHF 058	Responsive	Responsive	-----
	M/s.R.Madhusudhanan <b>Make-</b> R.Madhusudhanan <b>Model-</b> RM-11	Non-Responsive	Responsive	<b>Technical Evaluation:</b> Based on the specialist report the bidder is not meeting the following: 1. The sample produced is made out of reused materials, the workmanship and powder coating are of poor quality.

Brief Description	Name of the bidders	Responsiveness		Reason for rejection
		Technical Evaluation	Commercial evaluation	
	M/s.Solokrafts Industries <b>Make-</b> Solokrafts Industries <b>Model-</b> KRAFT 402A	Responsive	Responsive	-----

**Sch.III-Examination Couch:-**

Brief Description	Name of the bidders	Responsiveness		Reason for rejection
		Technical Evaluation	Commercial evaluation	
<b>Examination Couch</b>	M/s.BHN Surgicals Private Limited <b>Make-</b> BHN Surgicals Private Limited <b>Model-</b> MW-42(B)	Non-Responsive	Responsive	<b><u>Technical Evaluation:</u></b> Based on the specialist report the bidder is not meeting the following: 1. Overall size- Length 72", width- 27", height- 28" approx. 2. Top sheet- Stainless steel double press bent in 2 sections.
	M/s.Carewell Medical Systems <b>Make-</b> Carewell Medical Systems <b>Model-</b> CMS009	Responsive	Responsive	-----
	M/s.Imedfurns Private Limited <b>Make-</b> Imedfurns Private Limited <b>Model-</b> IMED5701T	Responsive	Responsive	-----
	M/s.Prince Hospital Furniture (mfg) Co., <b>Make-</b> Prince <b>Model-</b> PHF 050	Responsive	Responsive	-----
	M/s.R.Madhusudhanan <b>Make-</b> R.Madhusudhanan <b>Model-</b> Madhu-07	Non Responsive	Responsive	<b><u>Technical Evaluation:</u></b> Based on the specialist report the bidder is not meeting the following: 1. The sample produced is made out of reused materials, the workmanship and powder coating are of poor quality.

Brief Description	Name of the bidders	Responsiveness		Reason for rejection
		Technical Evaluation	Commercial evaluation	
	M/s.Samar Steel Industries <b>Make-</b> Samar Steel Industries <b>Model-</b> SSI-HF-109	Non-Responsive	Responsive	<b>Technical Evaluation:</b> Not demonstrated
	M/s.Solokrafts Industries <b>Make-</b> Solokrafts Industries <b>Model-</b> KRAFT 202B	Responsive	Responsive	-----

**Sch.IV-Bed Side Locker:-**

Brief Description	Name of the bidders	Responsiveness		Reason for rejection
		Technical Evaluation	Commercial evaluation	
<b>Bed Side Locker</b>	M/s.BHN Surgicals <b>Make-</b> BHN Surgicals Private Limited <b>Model-</b> MW-13 BEDPrivate Limited	Responsive	Responsive	-----
	M/s.Carewell Medical Systems <b>Make-</b> Carewell Medical Systems <b>Model-</b> CMS012	Responsive	Responsive	-----
	M/s.Imedfurns Private Limited <b>Make-</b> Imedfurns Private Limited <b>Model-</b> IMED6004	Responsive	Responsive	-----
	M/s.Prince Hospital Furniture (mfg) Co., <b>Make-</b> Prince <b>Model-</b> PHF 035	Responsive	Responsive	-----
	M/s.R. Madhusudhanan <b>Make-</b> R.Madhusudhanan <b>Model-</b> Madhu-017	Non Responsive	Responsive	<b>Technical Evaluation:</b> Based on the specialist report the bidder is not meeting the following: 1. The sample produced is made out of reused materials, the workmanship and powder coating are of poor quality.

Brief Description	Name of the bidders	Responsiveness		Reason for rejection
		Technical Evaluation	Commercial evaluation	
	M/s.Samar Steel Industries <b>Make-</b> Samar Steel Industries <b>Model-</b> SSI-HF-107	Non-Responsive	Responsive	<b>Technical Evaluation:</b> Not demonstrated
	M/s.Solokrafts Industries <b>Make-</b> Solokrafts Industries <b>Model-</b> KRAFT 702A	Responsive	Responsive	-----

**Sd/-**  
**General Manager (E)**