

EVALUATION RESULT

Tender for fixing rate contract for supply and installation of Patient Trolley (Type I & II), Trauma Emergency Cot, Fowlers Cot and General Bed to various Government Institutions

Tender ref. 299/FUR/TRC/TNMSC/ENGG/2018, Dt. 03.04.2018

Sch. No. 1(a). Patient Trolley (Type-I)

Name of the bidder with model & make	Responsiveness		Reason for rejection if any
	Technical Evaluation	Commercial Evaluation	
M/s. Solokrafts Industries, Chennai Model: KRAFT 402(A) -Option - A Make: Own	Responsive	Responsive	Nil
M/s. R.Madhusudhanan Make: Own Manufacturing	Responsive	Responsive	Nil
M/s. Prince Hospital Furniture (Mfg) Co., Make: Own Manufacturing	Responsive	Responsive	Nil
M/s. Amirtha Health Make: Sri Ratna Engineering	Responsive	Responsive	Nil
M/s. Premier Hospital Steel Furniture (Mfg) Co., Make: Own Manufacturing	Responsive	Non - Responsive	Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish their confirmation for accepting the delivery schedule, payment terms, warranty terms and furnishing performance security. 2) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.
M/s. Midmark (India) Pvt. Ltd., Model: 1704+1752E+0166G Make: Own Manufacturing	Responsive	Non - Responsive	Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish their confirmation for accepting the delivery schedule, payment terms, warranty terms and furnishing performance security. 2) Did not furnish cash / Credit limit as called for in the tender. 3) Did not furnish document like order copy, performance certificate in order to evaluate

**Sd/-
General Manager**

Name of the bidder with model & make	Responsiveness		Reason for rejection if any
	Technical Evaluation	Commercial Evaluation	
			the past performance of the similar equipment.
M/s. Solokrafts Industries, Chennai Model: KRAFT 402(B) -Option - B Make: Own	Non - Responsive	Responsive	Reason for rejection on technical points: Did not demonstrate the quoted model.
M/s. South India Surgical Co. Ltd., Chennai Make: SISCO	Non - Responsive	Non - Responsive	Reason for rejection on technical points: Did not demonstrate the quoted model. Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.
M/s. Med Freshe Pvt. Ltd., Model: 50-7300D Make: Medikraft	Non - Responsive	Non - Responsive	Reason for rejection on technical points: Did not demonstrate the quoted model. Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.
M/s. Trikaya Coatings Pvt. Ltd., Nashik Make: Own Manufacturing	Non - Responsive	Non - Responsive	Reason for rejection on technical points: Did not demonstrate the quoted model. Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish their confirmation for accepting the delivery schedule, payment terms, warranty terms and furnishing performance security. 2) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.

Sd/-
General Manager

Sch. No. 1(b). Patient Trolley (Type-II)

Name of the bidder with model & make	Responsiveness		Reason for rejection if any
	Technical Evaluation	Commercial Evaluation	
M/s. Solokrafts Industries, Chennai Model: KRAFT 402(A) Hi Lo -Option - A Make: Own	Responsive	Responsive	Nil
M/s. R.Madhusudhanan Make: Own Manufacturing	Responsive	Responsive	Nil
M/s. Prince Hospital Furniture (Mfg) Co., Make: Own Manufacturing	Responsive	Responsive	Nil
M/s. Amirtha Health Make: Sri Ratna Engineering	Responsive	Responsive	Nil
M/s. Premier Hospital Steel Furniture (Mfg) Co., Make: Own Manufacturing	Responsive	Non - Responsive	Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish their confirmation for accepting the delivery schedule, payment terms, warranty terms and furnishing performance security. 2) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.
M/s. Solokrafts Industries, Chennai Model: KRAFT 402(B) Hi Lo -Option - B Make: Own	Non - Responsive	Responsive	Reason for rejection on technical points: Did not demonstrate the quoted model.
M/s. Solokrafts Industries, Chennai Model: KRAFT 400 -Option - C Make: Own	Non - Responsive	Responsive	Reason for rejection on technical points: Did not demonstrate the quoted model.
M/s. South India Surgical Co. Ltd., Chennai Make: SISCO	Non - Responsive	Non - Responsive	Reason for rejection on technical points: Did not demonstrate the quoted model. Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.

**Sd/-
General Manager**

Name of the bidder with model & make	Responsiveness		Reason for rejection if any
	Technical Evaluation	Commercial Evaluation	
M/s. Trikaya Coatings Pvt. Ltd., Nashik Make: Own Manufacturing	Non - Responsive	Non - Responsive	<p>Reason for rejection on technical points: Did not demonstrate the quoted model.</p> <p>Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:-</p> <ol style="list-style-type: none"> 1) Did not furnish their confirmation for accepting the delivery schedule, payment terms, warranty terms and furnishing performance security. 2) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.

Sch. No. 2 Trauma Emergency Cot

Name of the bidder with model & make	Responsiveness		Reason for rejection if any
	Technical Evaluation	Commercial Evaluation	
M/s. Confident Dental Equipments Pvt. Ltd., Model: CME-54 Make: Own Manufacturing	Responsive	Responsive	Nil
M/s. Midmark (India) Pvt. Ltd., Model: 1710+1752E+1752D Make: Own Manufacturing	Responsive	Non - Responsive	<p>Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:-</p> <ol style="list-style-type: none"> 1) Did not furnish their confirmation for accepting the delivery schedule, payment terms, warranty terms and furnishing performance security. 2) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.
M/s. South India Surgical Co. Ltd., Chennai Make: Prince Hospital Furniture (Mfg.) Co.,	Responsive	Non - Responsive	<p>Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:-</p> <ol style="list-style-type: none"> 1) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment to meet the eligibility criteria for past end user performance.

**Sd/-
General Manager**

Name of the bidder with model & make	Responsiveness		Reason for rejection if any
	Technical Evaluation	Commercial Evaluation	
M/s. R.Madhusudhanan Make: Own Manufacturing	Non - Responsive	Responsive	Reason for rejection on technical points: 1) Foot operated height adjustment hydraulic pump was very hard to operate. 2) Castor wheels not sturdy. 3) M.S storage tray not provided.
M/s. Samar Steel Industries, Jalgaon Make: Own Manufacturing	Non - Responsive	Responsive	Reason for rejection on technical points: Did not demonstrate the quoted model.
M/s. Amirtha Health Make: Sri Ratna Engineering	Non - Responsive	Responsive	Reason for rejection on technical points: 1) Foot operated height adjustment hydraulic pump was very hard to operate. 2) Four corner rubber buffers not provided. 3) M.S storage tray not provided.
M/s. Solokrafts Industries, Chennai Model: KRAFT 401 Make: Own	Non - Responsive	Responsive	Reason for rejection on technical points: 1) Foot operated height adjustment hydraulic pump is very hard to operate and poor quality. 2) The foot hydraulic pump for height adjustment was with ordinary iron water pipes subject to rusting at future.
M/s. Trikaya Coatings Pvt. Ltd., Nashik Make: Own Manufacturing	Non - Responsive	Non - Responsive	Reason for rejection on technical points: Did not demonstrate the quoted model. Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish their confirmation for accepting the delivery schedule, payment terms, warranty terms and furnishing performance security. 2) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.
M/s. Med Freshe Pvt. Ltd., Model: 50-7400D Make: Medikraft	Non - Responsive	Non - Responsive	Reason for rejection on technical points: Did not demonstrate the quoted model. Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.

Sd/-
General Manager

Sch. No. 3. Fowlers Cot

Name of the bidder with model & make	Responsiveness		Reason for rejection if any
	Technical Evaluation	Commercial Evaluation	
M/s. R.Madhusudhanan Make: Own Manufacturing	Responsive	Responsive	Nil
M/s. Prince Hospital Furniture (Mfg) Co., Make: Own Manufacturing	Responsive	Responsive	Nil
M/s. Amirtha Health Make: Sri Ratna Engineering	Responsive	Responsive	Nil
M/s. Solokrafts Industries, Chennai Model: KRAFT 103 Make: Own	Responsive	Responsive	Nil
M/s. Premier Hospital Steel Furniture (Mfg) Co., Make: Own Manufacturing	Responsive	Non - Responsive	Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish their confirmation for accepting the delivery schedule, payment terms, warranty terms and furnishing performance security. 2) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.
M/s. Midmark (India) Pvt. Ltd., Model: BX4000+0195D+0236+0181+1040 Make: Own Manufacturing	Responsive	Non - Responsive	Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish their confirmation for accepting the delivery schedule, payment terms, warranty terms and furnishing performance security. 2) Did not furnish cash / Credit limit as called for in the tender. 3) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.
M/s. Samar Steel Industries, Jalgaon Make: Own Manufacturing	Non - Responsive	Responsive	Reason for rejection on technical points: Did not demonstrate the quoted model.
M/s. South India Surgical Co. Ltd., Chennai Make: SISCO	Responsive	Non - Responsive	Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish document like order copy, performance certificate in order to evaluate

**Sd/-
General Manager**

Name of the bidder with model & make	Responsiveness		Reason for rejection if any
	Technical Evaluation	Commercial Evaluation	
			the past performance of the similar equipment.
M/s. Med Freshe Pvt. Ltd., Model: 50-0500DH Make: Medikraft	Non - Responsive	Non - Responsive	Reason for rejection on technical points: Did not demonstrate the quoted model. Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.
M/s. Trikaya Coatings Pvt. Ltd., Nashik Make: Own Manufacturing	Non - Responsive	Non - Responsive	Reason for rejection on technical points: Did not demonstrate the quoted model. Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish their confirmation for accepting the delivery schedule, payment terms, warranty terms and furnishing performance security. 2) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.

Sch. No. 4. General Bed

Name of the bidder with model & make	Responsiveness		Reason for rejection if any
	Technical Evaluation	Commercial Evaluation	
M/s. R.Madhusudhanan Make: Own Manufacturing	Responsive	Responsive	Nil
M/s. Prince Hospital Furniture (Mfg) Co., Make: Own Manufacturing (SS)	Responsive	Responsive	Nil
M/s. Prince Hospital Furniture (Mfg) Co., Make: Own Manufacturing (MS powder coated)	Responsive	Responsive	Nil
M/s. Amirtha Health Make: Sri Ratna Engineering	Responsive	Responsive	Nil
M/s. Solokrafts Industries, Chennai Model: KRAFT 151 Make: Own	Responsive	Responsive	Nil

**Sd/-
General Manager**

Name of the bidder with model & make	Responsiveness		Reason for rejection if any
	Technical Evaluation	Commercial Evaluation	
M/s. Premier Hospital Steel Furniture (Mfg) Co., Make: Own Manufacturing	Responsive	Non - Responsive	Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish their confirmation for accepting the delivery schedule, payment terms, warranty terms and furnishing performance security. 2) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.
M/s. South India Surgical Co. Ltd., Chennai Make: SISCO	Non - Responsive	Non - Responsive	Reason for rejection on technical points: Did not demonstrate the quoted model. Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.
M/s. Trikaya Coatings Pvt. Ltd., Nashik Make: Own Manufacturing	Non - Responsive	Non - Responsive	Reason for rejection on technical points: Did not demonstrate the quoted model. Reason for rejection on Commercial points: Even after giving sufficient time the bidder does not furnish the following documents / confirmation:- 1) Did not furnish their confirmation for accepting the delivery schedule, payment terms, warranty terms and furnishing performance security. 2) Did not furnish document like order copy, performance certificate in order to evaluate the past performance of the similar equipment.

Sd/-
General Manager